



U. S. Steel
Clairton Works
400 State Street
Clairton, PA 15025-1855

RECEIVED

AUG 3 1994

July 29, 1994 DEVELOPMENT SECTION
EPA Region III

Mr. William Clark
Air Pollution Control Engineer
Allegheny County Health Department
Department of Air Quality
301 Thirty-Ninth Street, Building No. 7
Pittsburgh, PA 15201

Director
Air Toxics and Radiation Division
U. S. EPA Region III
841 Chestnut Street
Philadelphia, PA 19107

SUBJECT: Summary Reports - Leak Detection and Repair of Equipment in Benzene Service
USS Clairton Works, Clairton, Pennsylvania

Gentlemen:

Please find enclosed two copies each of the following benzene NESHAPS monitoring reports:

Leak Detection and Repair of Equipment in Benzene Service for the Period June 1991
through November 1991.

Leak Detection and Repair of Equipment in Benzene Service for the Period December 1991
through May 1992.

Leak Detection and Repair of Equipment in Benzene Service for the Period June 1992
through December 1992.

These reports summarize the results of the monitoring of equipment in benzene service for
fugitive emissions at USS Clairton Works facility located in Clairton, Pennsylvania. These
reports have been prepared to satisfy the requirements promulgated by 40 CFR 61 Subparts L
and V.

An audit of our records could not document that these reports had been submitted previously.
We are re-submitting these reports to assure that your files are complete.

If you have any questions regarding this package, please call me at (412) 233-1101.

RECEIVED

AUG 02 1994

AIR ENFORCEMENT BRANCH
EPA Region III

HRM/MS-94271
Attachments

Sincerely,

H. R. McCollum
H. R. McCollum
Manager Environmental Control



U. S. Steel Group
A unit of USX Corporation

SENT TO FILE ROOM
M.F.F. 12-01-94

ED_002508A_00000362-00001